


Fujita Retrofit Method for Factories



Steel Reinforcing Method with reduced welding

The Fujita retrofit method for factories (FSR-D method, WT clamp method) shortens the construction by reducing the need welding work.




FSR-D method

FSR-D is a method that connects reinforcing steel plates to existing members using self-drilling tapping screws.




screw part



WT clamp method

WT clamp method reinforces trussed girder.





Both method have acquired third party performance certification

FUJITA CORPORATION